



MEYLE No.

Referenz No.

Bushing Control arm, right Control arm, left 300 311 2104/HD 316 050 0008/HD 316 050 0007/HD 31 12 6 769 715 31 12 6 769 718 31 12 6 769 717

## Control arm bushing to fit BMW E53 (X5)









High dynamic strain causes leakage of the hydro-liquid

## **Effect**

- Vibration in the steering
- Reduced driving comfort





Replacing the hydro mount with a full rubber mount

## **Advantage**

No leakage possible and significant longer lifetime without restriction of driving comfort



