



MEYLE No.

Referenz No.

Bushing

300 311 2914/HD

31 12 1 092 010 31 12 9 068 753

Control arm, right Control arm, left 316 050 3904/HD 316 050 3903/HD 31 12 1 141 718 31 12 1 141 717

Control arm bushing to fit BMW E39, E52 (Z8)









High dynamic strain causes leakage of the hydro-liquid

Effect

- Vibration in the steering
- Reduced driving comfort





Replacing the hydro mount with a full rubber mount

Advantage

No leakage possible and significant longer lifetime without restriction of driving comfort

