





300 371 2102/HD 37 12 1 129 867

Strut mount, rear axle to fit BMW E32, E34









Problem

Failure of the rubber to metal compound between the inner bushing and the housing

Effect

Loud noise and reduced driving and braking safety





- Reinforcement of the rubber to metal compound by redesigning the inner sleeve
- Critical section is reinforced with more rubber

Advantage

Significant longer lifetime and driving comfort







