





100 610 0024/HD

7L0 407 182 G

Control arm bushing to fit Audi Q7, VW Toureg









Problem

Leakage of hydro fluid due to high dynamic loads and only partial rubbermetal bond



Noise and reduced driving and braking safety





Replacement of the hydromount with an optimized all-rubber mount with a generously-dimensioned rubber-metal bond

Advantage

No leakage possible and significant longer lifetime without restriction of driving comfort





MEYLE-HD-version

