



MEYLE No.

Control arm, left Control arm, right

316 050 0003/HD 31 12 6 774 819 316 050 0004/HD 31 12 6 774 820

Ball joint, left + right, short/outside Ball joint, left + right, long/middle

316 010 0003/HD 31 12 6 758 510 316 010 4305/HD

Set of brackets incl. rubber bushings Rubber bushing set, control arm 300 311 2604/HD 31 12 6 757 623 300 311 2919/HD

Reference No.

Repair kit

316 050 0000/HD 31 12 6 758 623 316 050 0000

Control arm to fit **BMW E46**











NTROL ARMS ARE

Loose ball joints that cannot be replaced individually



Effect

- Disturbing noises and vibrations
- · Complete control arm including ball joints must be replaced. Alignment is necessary





- Reinforced aluminum control arm with exchangeable ball joints
- Full-metal ball joint with longer service life

Advantage

- Inexpensive to replace each ball joint using standard tools
- · Distinct higher durability is guaranteed (TÜV tested)
- Many more miles of dependable driving pleasure