



MEYLE No.

Reference No.

316 020 0005/HD

32 10 6 774 335 32 21 6 760 354

Tie rod end to fit BMW E53 (X5)





Ball joints fail prematurely due to intense strain

Effect

Noise and play in the steering





Use of extremely long-wearing plastic ball joint sockets (in aviation tried and tested material)

Advantage

Significant longer lifetime