





MEYLE No.

Reference No.

300 331 7601/HD

33 17 6 751 808

Rubber mount for rear axle carriers **BMW E46, Z4, X3**









Leakage of hydro fluid due to high dynamic loads and only partial rubber-metal bond

Effect

Noise and reduced driving and braking safety





Replacement of the hydromount with an optimized all-rubber mount with a generously-dimensioned rubber-metal bond

Advantage

Longer service life without impairing safety or comfort





MEYLE - Miles in Motion